

Exhibit X



Form Response Items

Item	Value
1 9.2 Near Miss Report	
1.1 Near Miss subject	Loss of Satellite Compass
1.2 Choose appropriate level for near miss:	Continue and Report
1.3 Location:	Cape Hatteras
1.4 Reported by (Optional):	Christopher (Chris) L. Miller
1.5 Description of Near Miss:	Satellite Compass failed, causing the Auto pilot to go into standby and Hard right to Heavy Seas.
1.6 Actions Taken to Prevent Repeat of Incident:	Stand diligent watches, maintain electronics.
2 Office Use ONLY	Approved on 04/19/2024 08:15
2.1 Received date:	04/19/2024
2.2 Received by:	Brian Moore
2.3 Lessons learned created? (employee who is approving this near miss shoreside should also complete the Lessons Learned form-9.7- in correlation with this near miss).	No
2.4 Relevant section of TSMS:	

2.5 Remedial activities or training required:

1904

We had technicians come in and completely swap all the electronics that's associated with the navigation. Since the replacement, all components are fully operational.

2.6

Risk Severity Probability: